



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program October 20, 2009

Reviewed: 

Mine Name: Southern White/ Mountain Rose	Permit Number: S/001/0047
Operator Name: Great American Resources, LLC	Inspection Date: April 21, 2009
Inspector(s): Tmunson, WWestern	Time: 2pm
Other Participants: none	Mine Status: Inspect

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 9/29/2009 **Bond Amount:** \$18,600 **Permit fee** is delinquent


**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a small mine site on 04/21/2009

**Inspection Summary:** The site was not active at the time of inspection. There are many piles of various sized crushed materials of both the rose colored and the white marble. The site has expanded since our last inspection and it is would be appropriate for the operator to start thinking about the paperwork for a large mine. We did not GPS the site at this inspection due to a GPS malfunction.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

OGM to continue annual inspections and monitor the site when in the area. The operator needs to pay his annual fees for 2009 and consider a large mine permit before a noncompliance is issued for being greater then five acres.

**Inspector's Signature**  11/10/2009

cc: Gary Applegate

O:\M001-Beaver\S0010047-SouthernWhite-MtnRose\inspections\Insp-04212009.doc





Whole site, lower stockpile area, two quarry sites



stockpiles



White marble quarry face



Rose marble quarry site